


Artcut2009 software contains two parts (software disc and graphic disc), as below



Now, let us install it step by step.



1, Install software disc, like follows, put software into disk driver.






2, Click "my computer-mobile equipment-setup"





According default, click "next or yes" step by step.








You can click “browse” to choose one folder.



When you finish it, and click Artcut2009, it will pop up one dialog box.







3, Now let us put graphic disc into disk driver.





4, Click "my computer-mobile equipment-setup"

Please follow the default and install it.













5, When you want to output object, you can follow below steps after installing USB drivers.

a, Connecting cutting plotter with computer.


b, Open the computer "device manager", Reset the port number(choose com2).



Click mouse right button, open the “properties”.




Flow control choose “Xon/Xoff”, Then you choose “advance”, and choose port, usually you can choose “com2”.




6, After choosing “com2” in computer, you can open the artcut2009 software, you link to “com2”(Notice: please open artcut until you finish the selection about computer USB port).


7, Now Artcut2009 can be used. You can use it.



When you want to output it, it will pop up following dialog box or click left “device”.




It will warn you install cutting plotter, you can choose "Red sail" in manufactures, choose " Red sail(HPGL)/ (DMPL) " one by one in device, and add it.




About software installation, it's ending. When cutting plotter works, usually use "HPGL".

4, When you output object, you link to "com2", and choose right "setup", it will pop up following dialog box




Click "parameter",



Set like above picture. After finishing selection about “sequential control”, you will go back this page, and click “change”.

Note: You must click “change” after you change setting.



Then you can cut/plot.

Hope these information can help you.

Thanks for your patience.